Roads and Highways Advisory Group

Theft of Metal Drain Covers Durham County Council's Experience

Charlie Rand- Area Manager

charlie.rand@durham.gov.uk





Issue

Theft of Gully Grates sporadically throughout the county





Facts

- Number of gullies in the County 105,000
- Number of thefts in the last year 1100
- Cost to the authority
 - £137,500 to make safe (average cost £125 per gully)
 - Average £1,000 for effective repair

(£500 for cover and frame replacement & £1,200 for new gully with cover and frame)



Risks

Potentially lethal to:

- Pedestrians Personal injury
- Cyclists Personal injury and cycle damage
- Motorists Vehicle damage



DURHAM SON COUNCIL SOUNCIL SOUNCIL SOUNCIL SOUNCIL SON COUNCIL SON

Temporary Repairs

- Traffic Cone
- Plastic grating cut and placed to cover the void
- Large gullies sandbags used to fill the void



DURHAM SON SOUNCIL SOU

















Discussion

Reported in August's Surveyor Magazine

- Durham are not the only authority with this problem
- •Others include: Newcastle, Sunderland, Essex & Cardiff

National Problem?

Where do thefts stop? Signs, poles etc?





Positive Outcomes

- Police been pro-active by informing all scrap dealers to be aware of situation
- n Recently there have been positive prosecutions



